

CAT	CL.	MAINT. MANUAL	MANUFAC.	MODEL		DESCRIPTION
X2	1	KHF 950 Rev 2	Honeywell	KAC 952	Repair	HF Power / Amplifier Coupler
X2	1	KHF 950 Rev 2	Honeywell	KCU 951	Repair	HF Control unit
X2	1	006-15668-0009 Rev 9	Honeywell	KFS 598	Repair	Comm Controller
X2	1	KHF 950 Rev 2	Honeywell	KTR 953	Repair	HF / SSB Receiver
X2	1	006-00184-0006 Rev 6	Honeywell	KR 87	Repair	ADF Rx
X2	2	006-05639-0004 Rev 4	Honeywell	KFS 586	Repair	ADF Controller
X2	2	006-05624-0004 Rev 4	Honeywell	KFS 586A	Repair	ADF Controller
X2	2	006-05575-0000 Rev 0	Honeywell	KFS 594	Repair	HF Controller
X2	2	006-05511-0008 Rev 8	Honeywell	KDF 806	Ltd	ADF Receiver
X2	2	006-5005-06 Rev 6 (KNR 600)	Honeywell	KFS 560	Ltd	NAV Controller
X2	2	006-15645-0013 Rev 13	Honeywell	KFS 564	Repair	NAV Controller
X2	2	006-15646-0014 Rev 14	Honeywell	KFS 564A	Repair	NAV Controller
X2	3	006-5100-01 Rev 1	Honeywell	KFS 570B	Ltd	ATC Transponder Controller
X2	3	006-15545-0003 Rev 3	Honeywell	KT 76C	Repair	Transponder
X2	4	006-05332-0003 Rev 3	Honeywell	ART 2000	Ltd	Weather Radar Sensor
X2	4	006-00648-0002 Rev 2	Honeywell	ART 2100	Ltd	Weather Radar Sensor
X2	4	006-05920-0003 Rev 3	Honeywell	IN-152A	Repair	Radar Indicator
X2	4	IB8029079 Rev 5	Honeywell	AP-4001	Ltd	Antenna Pedestal
X2	4	006-05998-0002 Rev 2	Honeywell	IN 842A	Repair	Color Radar Indicator
X2	4	006-05998-0002 Rev 2	Honeywell	RDS 84	Ltd	Radar System
X3	4	006-5167-00 Rev 0	Honeywell	KAS 297	Repair	Altitude Selector
X3	4	006-05512-0003 Rev 3	Honeywell	KAS 297A	Repair	Altitude Selector / Alerter
X3	2	Lanseria	Honeywell	KCP 320		Flight Computer
X3	4	006-05111-0006 Rev 6	Honeywell	KCS 55 / 55A	O/H	Pictorial Navigation System
X3	1	Lanseria	Honeywell	KMC 340	Repair	Mode Controller
X3	1	006-15698-0008 Rev 8	Honeywell	KI 228/227	Repair	ADF Indicator
X3	1	006-5602-02 Rev 2	Honeywell	KPI 552 / 553 / A .	Ltd	Pictorial Navigation Indicator
X3	1	Lanseria	Honeywell	KS 270	Repair	Pitch Servo
X3	1	Lanseria	Honeywell	KS 270 A	Repair	Pitch Servo
X3	1	Lanseria	Honeywell	KS 271	Repair	Roll Servo
X3	1	Lanseria	Honeywell	KS 271A	Repair	Roll Servo
X3	1	Lanseria	Honeywell	KS 271C	Repair	Servo
X3	1	Lanseria	Honeywell	KS 272	Repair	Trim Servo
X3	1	Lanseria	Honeywell	KS 272A	Repair	Trim Servo
X3	1	Lanseria	Honeywell	KS 273	Repair	Servo
X3	1	Lanseria	Honeywell	KSA 370	Repair	Servo Actuator
X3	1	Lanseria	Honeywell	KSA 371	Repair	Servo Actuator

CAT	CL	MAINT. MANUAL	MANUFAC.	MODEL		DESCRIPTION
X2	4		Honeywell	RT-4001	Ltd	Weather Radar Indicator
X2	4	006-05600-0001 Rev 1	Honeywell	KWX 56	Repair	Radar system
X2	1	006-05204-0003 Rev 3	Honeywell	KRA 10/A	Repair	Rad Alt
X2	1	006-05104-0003 Rev 3	Honeywell	KRA 405/A/B	Repair	Rad Alt
X2	1	006-01540-0005 Rev. 5	Honeywell	KI 208/209	Repair	Nav Indicator
X2	1	006-05695-0004 Rev.5	Honeywell	KY 196A/197A	Repair	VHF Com
X2	1	006-05674-0005 Rev. 5	Honeywell	KY 96/97	Repair	VHF Com
X2	1	006-05695-0004 Rev 4	Honeywell	KY 96A/97A	Repair	VHF Com
X2	1	006-05169-0004 Rev.4	Honeywell	KY 196/E/197/E	Repair	VHF Com
X2	1	006-05174-0004 Rev 4	Honeywell	KN 53	Repair	VHF Nav Rx
X2	1	006-05096-0002 Rev 2	Honeywell	KNR 630/632	Repair	VHF Nav Rx
X2	1	006-15643-0012 Rev 12	Honeywell	KNR 634/ 634A	Repair	VHF Nav Rx
X2	3	006-Archive	Honeywell	KNS 80	Ltd	RNAV Rx
X2	3	006-Archive	Honeywell	KNS 81	Ltd	RNAV Rx
X2	3	006-05143-0008 Rev 8	Honeywell	KT 76A	Repair	Transponder
X2	3	006-05534-0001 Rev 1	Honeywell	KT 79	Repair	Transponder
X2	3	006-05615-0002 Rev 2	Honeywell	KT 71	Repair	Transponder
X2	3	006-00100-0000 Rev 0	Honeywell	KXP 755	Ltd	Transponder
X2	3	006-	Honeywell	KXP756	Ltd	Transponder
X2	2		Honeywell	KMA 24	Ltd	Audio/Marker
X2	2	006-05586-0003 Rev 3	Honeywell	KMA 24H	Repair	Audio/IC
X2	2	006-15544-0001 Rev 1	Honeywell	KMA 26	Ltd	Audio
X2	2		Honeywell	KMA 28	Ltd	Audio
X2	2	200-890-5464Rev 1	Honeywell	KMA 30	Ltd	Audio
X2	3	006-05144-0006 Rev 6	Honeywell	KN 62/62A	Repair	DME
X2	3	006-05176-0001 Rev 1	Honeywell	KN 63	Repair	DME
X2	3	006-05144-0006 Rev 6	Honeywell	KN 64	Repair	DME
X2	3	006-05177-0008 Rev 8	Honeywell	KDM 706/A	Repair	DME
X2	1	006-5019-04 Rev 4	Honeywell	KDF 805	Ltd	ADF
X2	1	006-05511-0008 Rev 8	Honeywell	KDF 806	Repair	ADF
X2	1	006-05137-0005 Rev 5	Honeywell	KI 206	Repair	Nav Indicator
X2	1	006-	Honeywell	KI 203/4	Repair	Nav Indicator
X2	2	006-05176-0001 Rev 1	Honeywell	KDI 572/3/4	Repair	DME Indicator
X2	1	006-05179-0009 Rev 9	Honeywell	KX 155/165	Repair	Nav/Com Transceiver
X2	1	006-15542-0002 Rev 2	Honeywell	KX 155A/165A	Repair	Nav/Com Transceiver
X3	1	006-15623-0007 Rev7	Honeywell	KG 102/A	Repair	Directional Gyro
X3	1	006-15635-0004 Rev 4	Honeywell	KSG 105	Repair	Directional Gyro
X3	1	15-3224-01 Sept 1979	Honeywell	VG-14 / 401	Repair	Vertical Gyro
X3	1	A09-3224-002 Rev 2 March 1999	Honeywell	VG-14A	Repair	Vertical Gyro

CAT	CL	MAINTENANCE MANUAL	MANUFAC	MODEL		DESCRIPTION
X2	1		Garmin	GTN 6XX/7XX	Ltd	Nav/Com/GPS
X2	1	190-00009-00	Garmin	GPS 100AVD	Ltd	GPS
X2	1	190-00067-25 Rev D	Garmin	GPS 155/165	Ltd	GPS
X2	1	190-00181-05 Rev G	Garmin	GNS 530	Ltd	GPS/Nav/Com
X2	1	190-00140-05 Rev F	Garmin	GNS 430	Ltd	GPS/Nav/Com
X2	1	190-00149-02 Rev B	Garmin	GMA 340	Ltd	Audio/Marker
X2	1	190-01007-A1 Rev 9	Garmin	GMA 35	Ltd	Audio/Marker
X2	1	190-01134-13 Rev A	Garmin	GMA 350	Ltd	Audio/Marker
X2	1	190-00853-00 Rev A	Garmin	SL 30/40	Ltd	VHF Nav/Com
X2	3	190-00187-05 Rev B	Garmin	GTX 327	Ltd	Transponder
X2	3	190-00207-02 Rev B	Garmin	GTX 330	Ltd	Transponder
X2	3	190-00207-05 Rev C	Garmin	GTX 335/345	Ltd	Transponder
X2	2		Collins	IDC-A09	Ltd	CD Player
X2	1	792-6657-001 Rev 2	Collins	VHF 20/A	Repair	VHF Transceiver
X2	1	523-0771854-30911A 9 Ed	Collins	VHF 22/A/C	Repair	VHF Transceiver
X2	1	523-0764700	Collins	VIR 30	Repair	VHF Nav Receiver
X2	1	523-0772819-1N611A	Collins	VIR 32	Repair	VHF Nav Receiver
X2	1	523-0773863-0W411A	Collins	VIR 432	Repair	VHF Nav Receiver
X2	1	523-0773785	Collins	VHF422/A/C	Repair	VHF Transceiver
X2	1	523-0772495	Collins	CTL X2/A/C	Repair	Controllers
X2	2	523-0770174-00411A	Collins	DME 40	Repair	DME Transceiver
X2	2	523-0772458-0C6111	Collins	DME 42	Repair	DME Transceiver
X2	2	522-4430-001	Collins	DME 442	Repair	DME Transceiver
X2	1		Collins	IND 42X	Repair	Indicator
X2	3	523-0765128-10911A	Collins	TDR 90	Repair	Transponder
X2	3	523-0775997-103113	Collins	TDR 94/D	Repair	Transponder
X2	1	523-0767346-101113	Collins	51RV1/5	Ltd	VHF Nav Receiver
X2	2	522-3698-002	Collins	860F-1/4	Ltd	Rad Alt
X2	1	523-0764898-221113	Collins	618M1/5	Ltd	VHF Transceiver
X2	4	523-0770194-00111A	Collins	WXT 200/250	Ltd	Weather Radar
X2	2	Rev Sept 2007 H2-6	ACK	E-01	Ltd	ELT
X3	1	B2-16 see below	Airpath	C-2300	O/H	Standby Compass
X3	1	NAVAER 05-15-606 Dec 1957	Airpath	C-2200-L4-B	O/H	Standby Compass
X2	2	570-5012 Rev F Apr 2010	Artex	G406-4	Repair	ELT
X2	2	570-1015 RevF Nov 1997 B2-14	Artex	ELT 110 Series	Ltd	ELT

CAT	CL	MAINTENANCE MANUAL	MANUFACTUR	MODEL	DESCRIPTION
X2	2	570-1600 Rev L Jun 2005 B2-12	Artex	ME-406 /HM	Repair ELT
X3	2		Artex		
X3	2	73-30-01 June 1980	Amtek	VSDL-OC208A/C	Repair Fuel Flow
			Ametek	ST502H	Ltd Torque Transmitter
X3	1	EO 20-15FE-2 April 1971	Aerosonic	RC-60-VIL-1	Ltd VSI
X3	1	O.M. Sept 1973	Aerosonic	1014XX	Repair Altimeter
X3	1		Aerosonic	1017XX	Repair Altimeter
X3	1	OM April 1975 H2-6	Aerosonic	1014XX	Repair Servoed Altimeter
X3	1	81-01/100 Nov1980 H4-8	Aeritalia	36101 / 8.148.0XX	Repair Gyro Horizon
X3	1	Rev c April 1983 H2-4	Aero Mech	AM 250	Repair Blind Encoder
X3	1	34-13-13 Jan 1978 H2-2	Aero Mech	8040/8140 Series	Repair Encoding Altimeter
X3	1	670-0044-001 Oct 1997	AIM / BFG	200/5 Series	O/H Directional Gyro
X3	1		AIM / BFG	210 Series	O/H Directional Gyro
X3	1		AIM / BFG	200-5	O/H Directional Gyro
X3	1		AIM / BFG	400/800 Series	O/H Slaved Gyro/RMI System
X3	1	670-0029-001	AIM / BFG	305 Series	Repair Attitude Indicator
X3	1		AIM / BFG	500EZ	Repair Horizon Indicator
X3	1		AIM / BFG	510 Series	Repair Attitude Indicator
X3	1		AIM / BFG	Autopilot A/H	Repair Attitude Indicator
X3	1	June 1985	AIM	100/300 Series	Repair Attitude Indicator
X3	1	March 1980	AIM	300-3/CF	Repair Attitude Indicator
X3	1	July 1975	AIM	300-7/9	Repair Flight Director
X3	1	March 1980	AIM	500 Series	Repair Attitude Indicator
X3	1	H4-6	AIM	TC-120	Ltd Turn Coordinator
X3	1	H4-6	AIM	TS-200-2	Repair Turn & Slip
X3	1	H4-6	AIM	TS-200-3A/B	Repair Turn & Slip
X3	1	H4-6	AIM	TS-200-4	Repair Turn & Slip
X3	1	H4-6	AIM	TS-300	Repair Vacuum Turn & Slip
X3	1		ARC	G-112A	Repair Directional Gyro
X3	1		ARC	G-113A/B	Repair Attitude Gyro
X3	1		ARC	G-212-A1	Repair Directional Gyro
X3	1	A10598 Rev 1 AUG 1996	Amtek	SELOC29DH	Repair Prop RPM Indicator
X1	2	F-17524 B2-15 H1-3	Barber-Colman	HYZ 50336-1	Repair Cabin Temp Controller
X1	1		Beech	M7921C-2B	Repair Blower Motor
X2	1		Beech	101-384028-1	Ltd Barometric Switch
X2	1	ATA 31-09 Feb 1982	Bendix	3571214-600X	Repair Torque Indicator
X3	1	70-7-1	Bendix	34108C1AF13-1A3	Repair Tachometer
X1	2	85-32-048 May 1985 H1-3	BF Goodrich	3D2991	Ltd De-icing Timer
X3	1	TP-218 Rev A Ch. 2 Apr 2001	BF Goodrich H4-5	AI-804	Repair Attitude Indicator

CAT	CL	MAINTENANCE MANUAL	MANUFACTURE	MODEL		DESCRIPTION
X3	1	H4-8	Cessna/SPD	SP-7576	Repair	Directional Gyro
X1	1	CMM 24-30-71	Cessna	C661064-0237	Repair	Airspeed Indicator
X1	1	68S54 Jan 1973	Century	Century III	Repair	Century II, IIB, III
X2	2	570-5012 Rev F Apr 2010 B2-14	Cobham	G406-4	Repair	ELT
X2	2	570-5000 Rev C APR 2010	Cobham	G406-2	Repair	ELT
X1	1	SM 68S51	Concorde	RG380 Series	Repair	Battery
X1	1	D3-TM 0037 Rev 17 Mar 2011	Dukane	DK 100/120	Repair	ULB
X1	1	D3-TM 0037 Rev 17 Mar 2011	Dukane	DK 130/140	Repair	ULB
X3	1	5-79-1 May 1979	Edo Aire	5000E	O/H	Attitude Gyro
X3	1	4-77-1	Edo Aire	5000L	O/H	Attitude Gyro
X3	1	H3-2	Edo Aire	1U367	Repair	Flight Director Indicator
X3	1	2-80-1 H4-9	Edo Aire	1U262 Series	O/H	DG (4000, 52D54)
X3	1	68S304 June 1976 J4-5	Edo Aire	NSD-360	Repair	HSI
X3	2	68S23 Rev1 Jan 1970	Edo-Aire	52D75-3/4	Repair	Turn & Slip
X3	2	68S73 Sept 1973 H4-2	Edo-Aire/Mitchell	52D69 / 75	Repair	Turn & Bank
X3	1	86M008 H4-9	Edo-Aire	4000C series	Repair	Directional Gyro-AP
X3	1	68S54 Jan 1973 J4-4	Edo-Aire/Mitchell	Century II,IIB&III	Repair	Auto pilot
X3	1	68S89 Sept 1977 J4-6/7	Edo-Aire/Mitchell	Century IV	Repair	Auto Pilot
X3	2	1085-5W July 1972	Edison	217-09261	Repair	Torque Indicator
X1	1	H1-10 / H1-9	Flite-Tronics	PC-6B	Ltd	DC to DC Converter
X1	1	H1-9	Flite-Tronics	PC-12A	Ltd	DC to DC Converter
X1	1	H1-10	Flite-Tronics	PC-15/A	Ltd	Inverter
X1	1	H1-10 Rev 5 July 1977 H1-6	Flite-Tronics	PC 17A-()	Ltd	Inverter
X1	1	H1-5 / H1-10 Rev 6 July 1966	Flite Tronics	PC 17	Ltd	Inverter
X1	1	24-20-03	Flite Tronics	PC-125	Ltd	Inverter
X1	1	24-20-03 Feb 1979 H1-6	Flite Tronics	PC-250	Ltd	Inverter
X1	1	24-20-04 May 1982 H1-5	Flite-Tronics	PC-350	Ltd	Static Inverter
		Aug 1975 H1-12	Foxbro	AR204A/AR207	Repair	Flow Rate
X3	2	5400 Dec 1978	General Design	5400-7425	Repair	Turn Coordinator
X3	2	H4-1 Jan 1970	General Design	2800 (4275-4)	Repair	Turn Coordinator
X1	1	4560K18-700A Feb 1968 H1-11	General Electric	DJ-64	Repair	Flowmeter
X3	2	77-10-19	General Electric	8DJ81	Repair	Tacho Indicator
X1	1	MM Q01-1120	Gill	Series	Repair	Lead Acid Batteries
X1	3	24-30-93	Goodrich	51538-001	Ltd	GCU
X1	2	Beech CMM 60-1750 CH.33-40.	Grimes	60-1750-3/7	Ltd	Strobe Pwr Supply

CAT	CL	MANUAL	MANUFAC.	MODEL	DESCRIPTION
X1	2	R1750 Rev 4 Sept 1984 H1-9	Grimes/Midland	60-1750 Ltd	Strobe
X3	3	98-36541 Jan 1984 J5-1	Gull	C90-E90-A100 Repair	Fuel Quantity System
X1	2		HBC	101-364580-1 Repair	Annunciator Control PCB
X2	1	J3-4	ICOM	IC-A200 Repair	VHF Transceiver
X3	2	35318 Dec 1980 H1-12	IDC	585-33986/7-() Repair	Fuel Temp / Control
X3	2	32624 Dec 1978 H1-11	IDC	585-31653-001/2 Repair	Fuel Flow
X3	2	35078 Feb 1982 H1-11	IDC	585-31653-013/4 Repair	Fuel Flow
X3	1	24313 Aug 1972	IDC	519-22702-() Repair	Encoding Altimeter
X3	2	24306 Dec 1972 H2-6	IDC	540-23989-() Repair	Altitude Alerter
X3	2	18996 Oct 1985 H2-6	IDC	23223 Series Repair	Altitude Alerter
X3	2	18989 Dec 1970	IDC	540-21100-() Repair	Altitude Alerter
X3	2	24315 reissue May 1982 B2-12	IDC	540-22722-() Repair	Altitude Alerter
X3	2	24881 Dec 1971	IDC / Kollsman	540-25100 Repair	Altitude Alerter
X3	1	34304 June 1979	IDC	523-29704-() Ltd	Encoding Altimeter
X3	1	28777 Sept 1977 H2-5	IDC	521-29007-() Repair	Encoding Altimeter
X3	1	28778 April 1976 H2-5	IDC	523-29702-() Repair	Encoding Altimeter
X1	1	43124 Feb 1985	IDC	570-23932-XXX Repair	Altimeter
X1	1	43128 Jan 1985	IDC	39499-A1131/B Repair	Altimeter
X1	1	43132 Oct 1984 H2-4	IDC	570-24929-400 Repair	Encoding Altimeter
X3	1	29531 May 1982	IDC	525-28711-() Repair	Servoed Altimeter
X3	1	43121 June 1984	IDC	520-15790 Repair	Servoed Altimeter
X3	1	27736 June 1975 H2-2	IDC	519-22702-500 Repair	Encoding Altimeter
X3	1	30579 Rev 4 Aug 1985 H2-2	IDC	518-28007-() Repair	Encoding Altimeter
X3	1	18916 Rev 2 June 1979 H1-8	IDC	518-16007-() Repair	Encoding Altimeter
X3	1	7026-58 H4-6	IDC / Brittan	TC100(12)(24) Repair	Turn Coordinator
		30581 March 1977 B2-12	IDC / Kollsman	519-28702-() Repair	Encoding Altimeter
X3	1	Rev A Nov 1987	Inst. Specialties	5032-() Repair	Turbine Temp
X3	1	TP-218 Sept 1989	J.E.T./ BFG	AI-804 Repair	Attitude Indicator
X3	1	TP-216 Feb 1986	J.E.T.	AI-904/AD Repair	Attitude Indicator
X1	1	TP-353 Oct 1985	J.E.T.	SC-841A Repair	Static Converter
X1	1	TP-329 Rev BC10 June 2012	J.E.T. / L3	PS-835() Repair	Emergency Power Supply
		DOC09078E Rev 4 Nov 2015	Kannad	AF Integra Ltd	ELT
X1	1	24-20-01 Mar 1984 J1-9	KGS	SPC-5 Ltd	Static Inverter
X1	1	Rev 3 Sept 1992 J1-9	KGS	PC-19 Ltd	DC to SQ Wave Inverter
X1	1	24-20-03 Rev 2 Sept 1994	KGS	SPC-10 Ltd	Static Inverter
X1	1	24-30-01 Rev2 Jul 1996 J1-6	KGS	LT-48() series Ltd	28 to 5V,DC Converter

CAT	CL	MANUAL	MANUFACT.	MODEL	DESCRIPTION
X1	1	24-20-00 July 1988 J1-6	KGS	SPS-306 series Ltd	Static Inverter
X1	1	24-20-13 Feb 1994	KGS	SPS-1307 series Ltd	Static Inverter
X1	1	Rev 2 March 1997	KGS	SPC-30() Ltd	Static Inverter
X3	2	45743 Dec 1986 H2-4	Kollsman	40535-() Repair	Baro Correct Alt Repeater
X3		AL-51	Kollsman	642K-05 Repair	Altimeter
X3		S175-500-450 Apr 1950	Kollsman	586CK Repair	ASI
		34-11-26 reissue June 75 B2-12	Kollsman	B45152-10-00X Repair	Encoder-Altimeter
X3		S1048-100-666 June 1966	Kollsman	A4017910025 Repair	Altimeter
X3		44603 Rev 1 Aug 1986	Kollsman	43010 Repair	VSI
X3	2	77-13-01 Aug 1973 H2-9	Kollsman	5278 Ltd	Tacho Generator
X3	2	46046 June 1986	Kollsman/IDC	39310-J1025 Repair	Airspeed/Mach Indicator
X3	1	46424 Dec 1986 H2-1	Kollsman/IDC	46807-K2331 Repair	Airspeed Indicator
X3	1	46054 July 1986 H2-1	Kollsman/IDC	39310-J2034 Repair	Airspeed/Mach Indicator
X3	1	43127 May 1985	Kollsman	534-35405-400/500 Ltd	Digital Mach Indicator
X3	1	46417 Oct 1986 H1-12	Kollsman/IDC	37470-0XX Repair	Fuel Used
X1	1	501-1228 Rev. B	L3	PS-835 O/H	Emergency Power Supply
X3	1	TDM 1904 Sept 1974	Lear Siegler	B0063 series Repair	Altimeter
X1	1	MM DCR59577	Marathon	Series Repair	Ni-Cad Batteries
X1	1	24-20-02 Jan 1992 H1-6	Marathon/Flite Tron	PC-125 Repair	Static Inverter
X3	1	Rev 8 Mar 2005 J5-4	Meggitt Avionics	28004 series Ltd	Encoding Altimeter
X3	2	79-32-40 Sept 1996	Meggitt Avionics	83-18()-1 Repair	Oil Pressure / Temperature
X3	2	77-12-40 Sept 1996 J5-9	Meggitt Avionics	41-201-1 Repair	Torque Indicator
X3	1	1310 Nov 1974	RC Allen	RCA 15 Repair	Directional Gyro
X3	1	1303 Jan 1969	RC Allen	RCA 11 Repair	Directional Gyro
X3	1	1309 Jan 1970	RC Allen	RCA 11A Repair	Directional Gyro
X3	1	1305 Jan 1969	RC Allen	RCA 21 O/H	Attitude Gyro
X3	1	1311 Dec 1975	RC Allen	RCA 25 O/H	Attitude Gyro Electric
X3	1	1317 May 1986	RC Allen	RCA 26XX O/H	Attitude Gyro Electric
X3	1	1307 Feb 1969	RC Allen	RCA 20 O/H	Attitude Gyro
X3	2	1200 Dec 1968 H4-2	RC Allen	RCA 30 Repair	Turn & Bank
X3	2	1302/4 Dec 1968	RC Allen	RCA 35 Repair	Turn & Bank
X1	2	30-80-03 Sept 1980 H1-3	Rosemount	871FA Ltd	Ice Detector
X1	1	MM F6177	SAFT	Series Repair	Aircraft Batteries
X3	2	31-09-109 Rev 2 Oct 1970 H1-4	Sangamo Weston	S.104	Ammeter or Voltmeter
X3	2	86M003 Mar 1982 H4-10	Sigma-Tek	1U407-001-1 Repair	Flight Director
X3	1	12-78-1 H4-10	Sigma Tek	5000B/D/F Repair	Attitude Gyro
X3	1	H4-10	Sigma Tek	5000E / 1U149 Repair	Horizon Gyro AP
X3	1	34-10-12 Dec 1972	Smiths	1100 AM Series Repair	Servoed Altimeter

CAT	CL	MANUAL	MANUFACT.	MODEL	DESCRIPTION
X3	2	31-09-50/50 Nov 1966	Smiths	666/1PG-1470/PG Repair	Torque Transmitters
X3	2	79-30-101-02 Apr 1968	Smiths	480PG/SB-1402PG/PU	Pressure Transmitters
X1	1	Rev 6 Nov 1964	Smiths	156/7PG Repair	Pressure Warning Switch
X3	1	SM-1002-0 May 1968	Standard Precision	SP-7581/2 series Repair	Gyro Horizon
X3	1	H4-8	Standard Precision	SP-7576/7 series Repair	Directional Gyro
X3	1	MC931C Rev C Mar 1976	Teledyne	SLZ9065-9706 Repair	IVSI
X3	1	MC88B Rev B Dec 1965	Teledyne	SLZ9123-9248 Repair	IVSI Integrally lighted
X3	1	7421 Rev D Aug 2006	T.C.I.	D120-P2-T(K) Repair	Alt Digitizer
X1	1	44 Rev 5 Oct 1969 H1-2	Thermal Control Co	TP350/1XX Repair	Low Pressure Switches
X3	2	34-10-32 March 1984 H2-3	Thommen	3A50/1 3A54/5 Repair	Altimeter/Encoding
X3	1	5932	United Instruments	UI-5932 Series Repair	Altimeter
X3	1	5934	United Instruments	UI-5934 Series Repair	Altimeter
X3	2	5035 H2-1	United Instruments	5035 / KEA130 Repair	Encoding Altimeter
X3	1	7000 Rev 0 May 1975	United Instruments	UI-7000 Series Repair	VSI
X3	1	8000B Aug 1986 H1-7	United Instruments	8000 Series Repair	Airspeed
X3	1	8200A March 1985 H1-7	United Instruments	8200 Series Repair	Airspeed
X3	1	8100BAug 1986	United Instruments	8100 Series Repair	True Airspeed
X3	2	9000 H4-1	United Instruments	9000/9100 series Repair	Turn Coordinator
X3	2	5035 Jan 1987 H1-7	United Instruments	5035 Repair	Encoding Altimeter
X3	2	9500 H4-1	United Instruments	9500/9550 series Repair	Turn & Slip
X2	2	Rev 3 May 1995 B2-5	Universal	UNS-1M Ltd	Nav Manage System
X2	2	Sept 1995 B2-4	Universal	UNS-1C Ltd	FMS
X3	2	Rev 1 June 1984 H1-2	Weston	S.122-4-XX Repair	Pressure Transmitter
X3	2	Aug 1975	Weston Instruments	1822 Repair	Flow Rate
X1	1	7-27-87/1 H1-9	Whelen	90033-() Ltd	Anti-collision Strobe



John Cole
Quality Manager



Bob Amey
Accountable Manager